



INTAKE DOOR ACTUATOR REPLACEMENT FOR NISSAN MAXIMA 98 W/O DASHBOARD REMOVAL

2024

Release/loose points



1. Remove the blower motor (not shown)



3a. Remove the Intake doors box





3b. Remove the Intake doors box




4. Intake box



Intake box parts



Actuator 27740-40U00 / 74100 30820



Actuator testing (door close/moving/open)

