

#1 - 61NIZZ1: EXT TRIM CONCERN
SINCE I PURCHASED THE VEHICLE IN 8-2018, IT HAS
HAD A SLIGHT RATTLE NOISE IMMITTING FROM THE REAR
PASSENGER SEAT/TRUNK AREA. I HAVE TROUBLESHOT FOR
HOURS, TO INCLUDE REMOVING ALL TRUNK/SPARE TIRE
ITEMS. AS THE WEATHER GETS COLDER, THE RATTLE HAS

Caused by

DUP TECH STATES ISOLATED SOUND TO RIGHT REAR
SHOCK AREA- **FOUND BUSHINGS ARE DEFORMED-** FOUND
NOISE COMING FROM SHOCK

Corrected by

Tech: HERIBERTO YEPEZ (034)

Installed 562183Z600 :BUSH-REAR SHOCK ABSORBER Qty: 1

Installed 562173Z600 :BUSH-REAR SHOCK ABSORBER Qty: 1

Installed E62104RA2A :SHOCK ABSORBER KIT REAR Qty: 1

REPLACED RIGHT REAR SHOCK AND BUSHINGS- TEST

DROVE NOISE IS GONE

Warranty

Warranty

Warranty

Warranty