

MECHANICKS Auto Repair
 1826 Millstream Rd
 Victoria BC V9B 6E3
 (250) 686-5070
 wrenchmonkey@hotmail.com



INVOICE

BILL TO

Teryl-lee Noble
 1992 Nissan Maxima
 jn1hj01c7nt002250
 Plate# HD653H

INVOICE # 3802
DATE 07/02/2024
DUE DATE 08/03/2024
TERMS Net 30

ACTIVITY	QTY	RATE	TAX	AMOUNT
Sales Vehicle inspection Instrument cluster inoperative new cluster required both left side window regulators and motors required Power steering fluid low multiple leaks Both cv axles required Complete exhaust flex pipe broken Rear exhaust manifold bolts broken Right rear caliper hanging up will need complete rear brakes front control arm forward bushings torn All rear control arm bushings splitting and weak All 4 struts original and soft Rear main seal leaking	1	100.00	GST/PST BC	100.00
Sales Shop supplies	1	5.00	GST/PST BC	5.00

SUBTOTAL	105.00
GST @ 5%	5.25
PST (BC) @ 7%	7.35
TOTAL	117.60
BALANCE DUE	\$117.60

TAX SUMMARY

	RATE	TAX	NET
GST @ 5%		5.25	105.00
PST (BC) @ 7%		7.35	105.00